ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| YELAHANKA | 6 | Thanisandra |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W0829, W0831, W0815, W0813 | NA, Panathur Colony Rd | Cauvery layout |
| **Segment No.** | **Total Length (m)** | |
| 6/C-W0829/S062903 | 31.14 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 31.14 | 77.633588 | 13.056671 | 77.633856 | 13.056606 | Cauvery layout | Shiva temple opp road |

### Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Improvements to roads and drains at Cauvery layout Dasarahalli in ward no. 06 Byatarayanapura sub division | 3000000 | 2015-16 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2015 - 2016 | Road | |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Tender | | 006-15-000030 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| BBMP/EE/BTP/WO/28/2016-17 | 05/04/2016 | |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 05/04/2016 | 05/04/2017 | No |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| Y.R. Sridhar | | 0.00 |
| **Phone No.** | **E-Mail ID** | |
| 9845182420 | | |

## Field Inspection Details

| Number of Trees | Any Other Information | Name |
|---|---|---|
| 1 | | daramasing c naik |

| Date of Inspection | Remarks |
|---|---|
| 02/05/2017 | |

| Category | Image | Photo Remark |
|---|---|---|
| Drain Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Segment Start | | This photo seems out of range. |
| Segment Start | | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | parameshwar | 04/05/2017 | 01/06/2017 | approved |
| SE | K.M.vasu | 04/05/2017 | 01/06/2017 | approved |
| EE | Mohan das | 04/05/2017 | 01/06/2017 | approved |
| AEE | B.S. Sridhar | 04/05/2017 | 01/06/2017 | approved |
| AE | Daramasingh c nayak | 02/05/2017 | 01/06/2017 | mobil verified |
| AE | Darmasingh C Nayak | 02/05/2017 | 01/06/2017 | |

**Zone:** YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0829, W0831, W0815, W0813

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

**Zone**
YELAHANKA

**Ward No.**
6

**Ward Name**
Thanisandra

**Street ID**
W0831, W0815, W0540, W0534

**Street Name**
Panathur Colony Rd, NA, 2nd Crs

**Significant Landmark**
Cauvery layout

**Segment No.**
6/C-W0831/S064131

**Total Length (m)**
54.62

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 54.62 | 77.633561 | 13.056206 | 77.633837 | 13.056313 | BCauvery layout BMP office Opp road to | 2nd and cross roads |

### Work Details

**History of Road / Lane / Circles**

**Name of the Work**
Improvements to roads and drains at Cauvery layout Dasarahalli in ward no. 06 Byatarayanapura sub division

**Sanctioned Estimated Amount (Rs.)**
3000000

**Sanctioned Year**
2015-16

**Year**
2015 - 2016

**Type of Work**

**Other Work Type**

**Tender**

**Work Details**

**Job No. / Work Code**
006-15-000030

**Work Order No.**
BBMP/EE/BTP/WO/28/2016-17

**Work Order Date**
05/04/2016

**Period of Extention**

**Defect Liability Period From**
05/04/2016

**Defect Liability Period To**
05/04/2017

**Multiple road involved with the same Job No/ Work Code #**
No

### Contractor Details

**Name of Contractor**
Y.R. Sridhar

**Contractor Reg No (BBMP/PWD)**

**Expenditure Booked \ Released (Rs)**
0.00

**Phone No.**
9845182420

**E-Mail ID**

## Field Inspection Details

**Number of Trees**

**Any Other Information**

**Name**

daramasing c naik

**Date of Inspection**

02/05/2017

**Remarks**

| Category | Image | Photo Remark |
|---|---|---|
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Segment Start |  | This photo seems out of range. |
| Segment Start | | This photo seems out of range. |
| Segment Start | | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | parameshwar | 04/05/2017 | 01/06/2017 | approved |
| SE | K.M.Vasu | 04/05/2017 | 01/06/2017 | approved |
| EE | Mohan das | 04/05/2017 | 01/06/2017 | approved |
| AEE | B.S. Sridhar | 04/05/2017 | 01/06/2017 | approved |
| AE | Daramasing C Nayak | 02/05/2017 | 01/06/2017 | mobil verified |
| AE | Darmasing C Nayak | 02/05/2017 | 01/06/2017 | |

**Zone:** YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0831, W0815, W0540, W0534